2.4 MD MECHANISM MODULE(2)



*One or two washers may be added to the parts for fine tuning of accuracy. When you exchange the parts such as (511: spin motor) or (1: motor spacer), mount it exactly as it was placed before the exchange.