


EXPLODED VIEW



*1: In order to maintain the waterproofing performance, the cord ASSY with plug cannot be replaced.

*2: The GPS unit cannot be replaced.

Parts with the exploded numbers larger than 700 are not supplied.