


# EXPLODED VIEW (UNIT)



About KDC-MP2055U :  
 PA1 does not exist as service part.  
 Instead, 223, 224 and 225 exist.

Parts with the exploded numbers larger than 700 are not supplied.


# EXPLODED VIEW (CD MECHANISM)

HCS-1100W

Block No.130

Grease

- ★ : W01-1737-08
- : W01-1738-08
- ▲ : W01-2007-08



Parts with the exploded numbers larger than 800 are not supplied.